



FIG. 1



10018430-122001

FIG. 2

A-A' CROSS SECTION



B-B' CROSS SECTION




FIG. 3






FIG. 4


A-A' CROSS SECTION



B-B' CROSS SECTION



C-C' CROSS SECTION



10018430 122001

FIG. 5






FIG. 6




10018430-1220001

7/21

FIG. 7



10018430-122001

FIG. 8

9/21

FIG. 9

A-A' CROSS SECTION





FIG. 10


B-B' CROSS SECTION



10018430-132001


11/21

FIG. 11



12 / 21

FIG. 12



10018430-122001

FIG. 13




FIG. 14

A-A' CROSS SECTION




FIG. 15

B-B' CROSS SECTION




FIG. 16




FIG. 17





FIG. 18



10018430-122001

FIG. 19





FIG. 21



10018430-120001